

**Aircraft:** N555RG | **Trip #:**96

**CharterMatrix**

**Customer:** Terry Cooper

Melbourne, FL 32904

Leg #	Flight Date	Pax #	AirPort ID		Block & Flight Time (z)				Flt Time	Fuel/lbs Burn	Land		Inst Time	Appr Type	Pilots	PT91 135	TOGW	CG	Miles
			From	To	Out	Off	On	In			Day	Ngt							
1	06/22/10	4	TEB	PBI	1150	1200	1435	1440	2.6	4567	1	0	.2	ILS	BD,MO	135	20500		902
2	06/23/10	4	PBI	TEB	1600	1610	1830	1835	2.4	4189	1	0	.4	VOR	BD,MO	PT91	20100		902
3																			
4																			
5																			
6																			
7																			
8																			
9																			
10																			
11																			
12																			
13																			
14																			

	Airframe	Landings	Engine 1	Cycles 1	Engine 2	Cycles 2	Engine 3	Cycles 3	APU	Cycles
<b>Fwd</b>	1027.8	121	1027.8	122	1027.8	122			103	103
<b>Flt</b>	5	2	5	2	5	2	N/A		1.1	2
<b>Total</b>	1032.8	123	1032.8	124	1032.8	124			104.1	105

**APU Hrs:** 1.1      **APU Cyc:** 2

**VOR check Date:** 6/1/2010  
**Nav 1 Bearing Error** 350  
**Nav 2 Bearing Error** 351  
**Identifier** GNV  
**Frequency** 116.35

**Notes**

Filled left engine with oil after landing.

<b>Expense Type</b>	<b>Amount</b>	<b>Name</b>	<b>Payment Type</b>	<b>Notes</b>
Catering	124.78	Bill Decker	Visa	
Ramp Fee	250.00	Bill Decker	American Express	Signature fee
Fuel	1450.00	N/A	Colt Fuel	\$4.11 gallon
Rental Car	150.00	Matthew Oleary	Master Card	Hertz
Hotels	288.00	Matthew Oleary	Master Card	Hilton for both rooms